

REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE (ER 1130-2-3165)					PAGE 1 OF 1		
					DATE 16 April 2002		
TO: The Record				FROM: U.S. Army Corps of Engineers 26 Federal Plaza, ATTN: CENAN-OP-ST New York, NY 10278-0090			
RIVER/HARBOR NAME AND STATE: TARRYTOWN HARBOR, NEW YORK					MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nmiles)	DEPTH (feet)			
SOUTH CHANNEL	19-20 MAR 02 FILE #23	150	0.32	12	7.7	8.3	7.5
WHARF	19-20 MAR 02 FILE #23	150 TO 250	0.36	12	7.7	7.3	6.8
NORTH CHANNEL	19-20 MAR 02 FILE #23	150	.33	12	8.3	10.1	9.1
REMARKS (Continue on reverse)							
-All depths are in Mean Low Water (MLW) -Shoaling extends across the entire channel width from 450 feet South of Green Can #3 in the South Channel to 450 feet North of Red NUN 4 in the North Channel.							